

SPECIAL COMPROMISE FINE	
Reference Number	Comp/0118/2025 (#1902)
Description	Rock Cut Limited
Locality	Luqa
Breach involved in this Case	1. Failed to ensure the physical and psychological wellbeing of your workers at all times and of all persons who may be affected by the work being carried out by your work activities as prescribed by Art. 12(1) of the Health and Safety at Work Act (Cap. 646 of the Laws of Malta). 2. Failed to take the necessary preventive measures on the basis of the general principles of prevention as prescribed by Art. 12(2) of the Health and Safety at Work Act (Cap. 646 of the Laws of Malta). 3. Failed to ensure that all scaffolding is designed so that it does not collapse or move accidentally and used in a way that prevents people from falling or being exposed to falling objects or inspected and certified by a competent person (LN 88/18) (LN 52/25). 4. Failed to take adequate and sufficient measures to prevent falls from height (LN 88/18) (LN 52/25). 5. Failed to subject work equipment to an initial inspection (after installation and before first being put into service) and an inspection after assembly at a new site or in a new location by a competent person (LN 293/16).
Date of Offence	20 th December 2024
Date of Payment	3 rd September 2026
Special Compromise Amount	€5,500

Industry	Construction	Main Activity	Construction
-----------------	--------------	----------------------	--------------

